
















REPLACEMENT FOR
IST '2005

REPLACEMENT FOR
YARIS '05-'06



SLTOYOTA

<p>SL322905001 HEAD LAMP L:81106-52520 R:81105-52520</p> 	<p>SL321605001 HEAD LAMP W/MOTOR L:81170-8C016 R:81130-8C016</p> 	<p>SL321605007 GRILLE 53111-0D170</p> 
<p>SL322905007 GRILLE</p> 	<p>SL321605005 TAIL LAMP L:81561-52480 R:81551-52550</p> 	<p>SL321605014 FRONT BUMPER GRILLE 53112-0D080</p> 
	<p>SL321605005-01 TAIL LAMP L:81561-0D110 R:81551-0D110</p> 	<p>SL321605042 AIR CLEANER 17700-21120</p> 
	<p>SL321605003 FOG LAMP L:81220-0D040 R:81210-0D040</p> 	<p>SL321605012 FRONT BUMPER 52119-0D999</p> 
	<p>SL3216050004 SIDE LAMP 81730-0D060</p> 	<p>SL321605044 REAR BUMPER 52159-0D985</p> 
	<p>SL321605015 FOG LAMP CASE L:81482-52110 R:81481-52150</p> 	<p>SL321605053 FRONT BUMPER SUPPORT</p> 