


















REPLACEMENT FOR
LANCER EVO '08

REPLACEMENT FOR
PAJERO MONTERO '00-'03 V73

<p>SL250809012 FRONT BUMPER</p> 	<p>SL250809051 HOOD</p> 	<p>SL250900001 HEAD LAMP L:MR 548035 R:MR 548036</p> 
<p>SL250809044 REAR BUMPER</p> 	<p>SL250809052 FENDER L: R:</p> 	<p>SL250903001 HEAD LAMP L:MN133753 R:MN133754</p> 
<p>SL250809088 GRILLE FRAME</p> 		<p>SL250900005 TAIL LAMP L:MR 508201 R:</p> 
<p>SL250809007 GRILLE</p> 		<p>SL250900005-01 TAIL LAMP L: R:MR 508504</p> 
<p>SL250809007-01 GRILLE W/H</p> 		<p>SL250903005 TAIL LAMP L: R:</p> 
<p>SL250809024 FENDER INNER L: R:</p> 		<p>SL250903005-01 TAIL LAMP L:MN133763 R:MN133764</p> 



REPLACEMENT FOR
PAJERO MONTERO '00-'03 V73

SLMITSUBISHI












<p>SL250903005-02 TAIL LAMP L: R:</p> 	<p>SL250900012 FRONT BUMPER</p> 	<p>SL250900051 HOOD</p> 
<p>SL250900003 FOG LAMP L:MR 508189 R:MR 508190</p> 	<p>SL250903012 FRONT BUMPER</p> 	<p>SL250900052 FENDER L: R:</p> 
<p>SL250903003 FOG LAMP MN133758</p> 	<p>SL250900044 REAR BUMPER</p> 	<p>SL250900054 FRONT DOOR L: R:</p> 
<p>SL250903077 REAR FOG LAMP L:MN133775 R:MN133776</p> 	<p>SL250903017 MUD GUARD SET</p> 	<p>SL250900055 MIDDLE DOOR L: R:</p> 
<p>SL250900007 GRILLE MR387981(2)</p> 	<p>SL250900024 FENDER INNER L: R:</p> 	<p>SL250900057 REAR DOOR</p> 
<p>SL250903007 GRILLE BLACK MN117202WA</p> 	<p>SL250900067 RADIATOR SUPPORT MR548340</p> 	<p>SL250900053 F.R BUMPER SUPPORT</p> 




REPLACEMENT FOR
PAJERO '02 MINI



REPLACEMENT FOR
PAJERO '07 V93

<p>SL250902001 HEAD LAMP L:MR414929 R:MR414930</p> 	<p>SL250902051 HOOD</p> 	<p>SL251407001 HEAD LAMP WO/MOTOR L: R:</p> 
<p>SL250902005 TAIL LAMP L:MR535073 R:MR535074</p> 	<p>SL250902052 FENDER L: R:</p> 	<p>SL251407003 FOG LAMP L: R:</p> 
<p>SL250902003 FOG LAMP L:MR439835 R:MR439836</p> 	<p>SL250902067 RADIATOR SUPPORT</p> 	
<p>SL250902007 GRILLE MR511943/4</p> 		
<p>SL250902012 FRONT BUMPER</p> 		
<p>SL250902044 REAR BUMPER</p> 		



REPLACEMENT FOR
PAJERO '07 V97

REPLACEMENT FOR
ASX '2010

SLMITSUBISHI

SL250907001

HEAD LAMP W/MOTOR HID
L:8301A893
R:8301A894



SL250907024

FENDER INNER
L:
R:



SL251210001

HEAD LAMP W/MOTOR
L:8301B587
R:8301B588



SL250907005

TAIL LAMP
L:8330A353
R:8330A354



SL250907014

BUMPER GRILLE



SL251210005

TAIL LAMP
L:8330A689
R:8330A690



SL250907003

FOG LAMP
8321A034 8321A144 MN142091



SL250907028

DOOR MIRROR
L 7632A655
R 7632A656



SL251210006

BACK LAMP
L:8336A087
R:8336A088



SL250907012

FRONT BUMPER



SL250907051

HOOD

SL251210003

FOG LAMP
8321A370



SL250907044

REAR BUMPER



SL250907052

FENDER
L:
R:

SL251210077

REAR FOG LAMP



SL250907007

GRILLE
7450A368



SL251210130

REFLECTOR

