

2020版



AUTO BODY PARTS & ACCESSORIES

丹阳赛领汽车部件有限公司

DANYANG SAILING AUTO PARTS CO.,LTD

[www.slautoparts.com](http://www.slautoparts.com)

# INDEX

REPLACEMENT FOR  
**QASHQAI '2017**

P1



REPLACEMENT FOR  
**QASHQAI '2014**

P2-3



REPLACEMENT FOR  
**QASHQAI '2010**

P3



REPLACEMENT FOR  
**JUKE '2010-**

P4



REPLACEMENT FOR  
**JUKE '2015-**

P5



REPLACEMENT FOR  
**MICRA '2014**

P5



REPLACEMENT FOR  
**VERSA '2015**

P6



REPLACEMENT FOR  
**ALMERA '16 00-05**

P6



REPLACEMENT FOR  
**ALMERA '10 06-12**

P7



REPLACEMENT FOR  
**COROLLA '2016**

P7-8



REPLACEMENT FOR  
**COROLLA '2010**

P8



REPLACEMENT FOR  
**COROLLA '08**

P9



REPLACEMENT FOR  
**CAMRY '07**

P10



REPLACEMENT FOR  
**AVALON '01-'04**

P10



REPLACEMENT FOR  
**AVALON '05-'07**

P10



REPLACEMENT FOR  
**LANCER '03-'06**

P8



REPLACEMENT FOR  
**LANCER '07**

P8



REPLACEMENT FOR  
**L300 '01**

P8













REPLACEMENT FOR  
**QASHQAI '2017**

REPLACEMENT FOR  
**QASHQAI '2017**

REPLACEMENT FOR  
**QASHQAI '2017**


















<p><b>SL262017001</b> <span style="color: red;">E-mark</span> HEAD LAMP LED HALOGEN L:26060-HV00A R:26010-HV00A</p> 	<p><b>SL262017014</b> FIN-FRT-BMP 62070-HV00A</p> 	<p><b>SL262017014S</b> BUMPER GRILLE SIDE BLACK L:62257-HV10B R:62256-HV10B</p> 
<p><b>SL262017001H</b> HEAD LAMP FULL LED L:26060-HV05B R:26010-HV05B</p> 	<p><b>SL262017012</b> FRONT BUMPER 62022-HV00H</p> 	<p><b>SL262017133</b> FR. COVER-BUMPER BR 622A0-HV00A</p> 
<p><b>SL262017005</b> <span style="color: red;">E-mark</span> TAIL LAMP LED L:26555-HV00A R:26550-HV00A</p> 	<p><b>SL262017012-H</b> FRONT BUMPER W/H 62022-HV20A</p> 	<p><b>SL262017112</b> COVER-HEAD LAMP L:28658-HV08E R:28659-HV08E</p> 
<p><b>SL262017006</b> <span style="color: red;">E-mark</span> TAIL LAMP INNER LED L:26555-HV05A R:26550-HV55A</p> 	<p><b>SL262017015</b> FOG LAMP CASE L:26915-HV00A R:26910-HV00A</p> 	<p><b>SL262017111</b> HEAD LAMP NOZZLE ASSY L:28612-HV00A R:28611-HV00A</p> 
<p><b>SL262017003</b> FOG LAMP W/O BULB L: R:</p> 	<p><b>SL262017104</b> WHEEL BROW FRONT L:63811-4EA0B R:63810-4EA0B</p> 	
<p><b>SL262017007</b> GRILLE 62310-HV00A 62310-HV10A</p> 	<p><b>SL262017105</b> WHEEL BROW REAR L:93829-4EA0A R:93828-4EA0A</p> 	



REPLACEMENT FOR  
**QASHQAI '2014**

REPLACEMENT FOR  
**QASHQAI '2014**

REPLACEMENT FOR  
**QASHQAI '2014**














<p><b>SL262014001</b> HEAD LAMP LED HALOGEN L:26060-4EH0B R:26010-4EH0B</p> 	<p><b>SL262014012</b> FRONT BUMPER 62022-4EA0H 62022-4EF0H</p> 	<p><b>SL262014104</b> WHEEL BROW FRONT L:63811-4EA0B R:63810-4EA0B</p> 
<p><b>SL262014005</b> <b>E-mark</b> TAIL LAMP L:26555-4EA0A R:26550-4EA0A</p> 	<p><b>SL262014012-H</b> FRONT BUMPER W/H 62022-4EA0H 62022-4EF0H 62022-4EF0H</p> 	<p><b>SL262014105</b> WHEEL BROW REAR L:93829-4EA0A R:93828-4EA0A</p> 
<p><b>SL262014006</b> <b>E-mark</b> TAIL LAMP INNER EU. TYPE L:26555-4EA5A R:26550-4EA5B</p> 	<p><b>SL262014133</b> COVER-BUMPER BR 622A0-4EA0A</p> 	<p><b>SL262014102</b> BOARD FRONT L:80871-4EA0A R:80870-4EA0A</p> 
<p><b>SL262014003</b> FOG LAMP W/O BULB 26150-89906 26150-8990B</p> 	<p><b>SL262014015</b> FOG LAMP COVER BLACK L:62257-4EA0B R:62256-4EA0B</p> 	<p><b>SL262014103</b> BOARD REAR L:82871-4EA0A R:82870-4EA0A</p> 
<p><b>SL262014007</b> GRILLE W/RADIATOR UPPER COVER W/H 62312-4EA0D 62310-4EM1D 62310-4EM1A</p> 	<p><b>SL262014015-1</b> FOG LAMP CASE W/CHROM MLDG L:62257-4EA0A R:62256-4EA0A</p> 	<p><b>SL262014025</b> ENGINE PROTECT LOWE 75892-4EA0A</p> 
<p><b>SL262014007-1</b> GRILLE W/RADIATOR UPPER COVER 62310-4EA1A 62310-4EM1A 62382-4EA0A 62382-4EM0A</p> 	<p><b>SL262014024</b> FENDER INNER L:63843-4EA0A R:63842-4EA0A</p> 	<p><b>SL262014112</b> COVER-HEAD LAMP L:28659-4EM8E R:28658-4EM8E</p> 




REPLACEMENT FOR  
**QASHQAI '2014**

REPLACEMENT FOR  
**QASHQAI '2010**

REPLACEMENT FOR  
**QASHQAI '2010**

<p><b>SL262014053-L</b> FR.BUMPER SUPPORT LOWER 62030-4EA0D</p> 	<p><b>SL262010003</b> FOG LAMP W/O BULB L:8200301026 R:8200301027</p> 	<p><b>SL262010112</b> COVER-HEAD LAMP L:28659-BR00H R:28658-BR00H</p> 
<p><b>SL262014067-U</b> RADIATOR SUPPORT UPPER F2511-4EAMH</p> 	<p><b>SL262010005</b> <b>E-mark</b> TAIL LAMP LED L:26555-BR00A R:26550-BR00A</p> 	
<p><b>SL262014067-S</b> RADIATOR SUPPORT UPPER SIDE L:F2521-4EAEA R:F2520-4EAEB</p> 	<p><b>SL262010006</b> <b>E-mark</b> TAIL LAMP INNER L:26559-BR01A 26555-BR01A R:26554-BR01A 26550-BR01A</p> 	
<p><b>SL262014067-S1</b> RADIATOR SUPPORT SIDE L:F2521-4EAMA R:F2520-4EAMA</p> 	<p><b>SL262010004</b> SIDE LAMP 26160-8990A</p> 	
<p><b>SL262014067-L1</b> RADIATOR SUPPORT LOWER F2530-DF3MH</p> 	<p><b>SL262010007</b> GRILLE 62310-BR10A</p> 	
<p><b>SL262014067-L</b> MEMBER -FRONT 54410-4EA1A 54410-4EB1A 54410-4EB1B</p> 	<p><b>SL262010126</b> FR.BUMPER BRACKET L:62223-BR00A R:62222-BR00A</p> 	



REPLACEMENT FOR  
**JUKE '2010-**

REPLACEMENT FOR  
**JUKE '2010-**

REPLACEMENT FOR  
**JUKE '2010-**












<p><b>SL262310003</b> FOG LAMP W/O BULB 26150-89906-21 26150-8990B</p> 	<p><b>SL262310024</b> FNNER INNER L:63843-1KA0A R:63842-1KA0A</p> 	<p><b>SL262310067U</b> RADIATOR SUPPORT UPPER 62511-1KM0H</p> 
<p><b>SL262310004</b> SIDE LAMP 26160-8990A</p> 	<p><b>SL262310104</b> WHEEL BROW FRONT L:63861-1KA6A R:63860-1KA6A L:63861-1KA0A R:63860-1KA0A</p> 	<p><b>SL262310067US</b> RADIATOR SUPPORT UPPER SIDE L:62521-1KA0A R:62520-1KA0A</p> 
<p><b>SL262310133</b> FR. COVER-BUMPER BR 622A0-1KA0A</p> 	<p><b>SL262310105</b> WHEEL BROW REAR L:78861-1KA6A R:78860-1KA6A L:78861-1KA0A R:78860-1KA0A</p> 	<p><b>SL262310067S</b> RADIATOR SUPPORT SIDE L:62523-1KA0A R:62522-1KA0A</p> 
<p><b>SL262310007</b> GRILLE 62070-1KA6A 62072-1KA6A</p> 	<p><b>SL262310126</b> FR.BUMPER BRACKET L:62223-BA60A R:62222-BA60A</p> 	<p><b>SL262310067L</b> RADIATOR SUPPORT LOWER 62530-1KM0H</p> 
<p><b>SL262310007S-L</b> GRILLE SIDE LH 62075-1KA6A</p> 	<p><b>SL262310127</b> RR.BUMPER BRACKET L:85229-BV80A R:85228-BV80A</p> 	
<p><b>SL262310007S-R</b> GRILLE SIDE RH 62074-1KA6A</p> 		



REPLACEMENT FOR  
**JUKE '2015-**

REPLACEMENT FOR  
**JUKE '2015-**

REPLACEMENT FOR  
**MICRA'2014**

<p><b>SL262315003</b> FOG LAMP W/O BULB L:26150-89926 R:26155-89926</p> 	<p><b>SL262315126</b> FR.BUMPER BRACKET L:62223-BV80A R:62222-BV80A</p> 	<p><b>SL262614007</b> GRILLE 62310-3HN0A/3A/5A/1A/4A/6A</p> 
<p><b>SL262315007</b> GRILLE 62072-BV83A 62072-BV80A 62072-BV81A 62072-BV82A</p> 	<p><b>SL262315127</b> RR.BUMPER BRACKET L:85229-BV80A R:85228-BV80A</p> 	<p><b>SL262614003</b> FOG LAMP W/O BULB L:8200301026 R:8200301027</p> 
<p><b>SL262315007S-L</b> GRILLE SIDE LH 62075-BV80A</p> 	<p><b>SL262315133</b> FR. COVER-BUMPER BR 622A0-BV80A</p> 	<p><b>SL262614004</b> SIDE LAMP 26160-8990A</p> 
<p><b>SL262315007S-R</b> GRILLE SIDE RH 62074-BV80A</p> 		
<p><b>SL262315104</b> WHEEL BROW FRONT L:63861-1KA6A R:63860-1KA6A L:63861-1KA0A R:63860-1KA0A</p> 		
<p><b>SL262315105</b> WHEEL BROW REAR L:78861-1KA6A R:78860-1KA6A L:78861-1KA0A R:78860-1KA0A</p> 		



®



REPLACEMENT FOR  
**VERSA '2015**

REPLACEMENT FOR  
**VERSA '2007**

REPLACEMENT FOR  
**ALMERA'N16 00-05/SUNNY 01**

**SL262516001**

HEAD LAMP LATIN AMERICA TYPE  
L:26060-9KM0A  
R:26010-9KM0A



**SL262507128-F**

FR. BUMPER ABSORBER  
62090-EM30A



**SL261301138**

PLATE TRUNK REAR  
83731-31000  
84992-4M500



**SL262515001**

HEAD LAMP USA TYPE  
L:26060-9KK0A  
R:26010-9KK0A



**SL262515003**

FOG LAMP W/O BULB  
L:26150-89926  
R:26155-89926















REPLACEMENT FOR  
**ALMERA'B10 06-12/SUNNY 07**

REPLACEMENT FOR  
**SUNNY'2004**

REPLACEMENT FOR  
**COROLLA '2016**



<p><b>SL261307024-R</b> REAR FENDER INNER/Rear bumper boot L:87271-31700 R:87272-31700</p> 	<p><b>SL261307138</b> PLATE TRUNK REAR</p> 	<p><b>SL320316003</b> FOG LAMP W/O BULB L:81220-0D100 R:81210-0D100</p> 
		<p><b>SL320316007</b> GRILLE EU. TYPE 53100-02700</p> 
		<p><b>SL320316007-1</b> GRILLE MIDDLE TYPE 53111-02B30 53100-02B80</p> 
		<p><b>SL320316012</b> FRONT BUMPER EU. TYPE 52119-0Z970</p> 
		<p><b>SL320316012-H</b> FRONT BUMPER W/H EU. TYPE 53112-02690</p> 
		<p><b>SL320316014</b> FR. BUMPER GRILLE EU. TYPE 53112-02690</p> 



REPLACEMENT FOR  
**COROLLA '2016**

REPLACEMENT FOR  
**COROLLA '2014**

REPLACEMENT FOR  
**COROLLA '2010**

<p><b>SL320316015</b> FOG LAMP CASE EU. TYPE L:81482-02620 R:81481-02630</p> 	<p><b>SL320314042</b> AIR CLEANER HOUSING 17700-37211 17700-0T101</p> 	<p><b>SL320310128-F</b> FR. BUMPER ABSORBER 52611-02250</p> 
<p><b>SL320316133</b> COVER-BUMPER BR FR. EU.TYPE 52127-02930</p> 		
<p><b>SL320316024</b> FENDER INNER EU. TYPE L:53876-02501 R:53875-02481</p> 		
<p><b>SL320316126</b> FR. BUMPER BRACKET EU. TYPE L:52116-02350 R:52115-02360</p> 		
<p><b>SL320316112</b> COVER-HEAD LAMP L:85354-02130 R:85353-02130</p> 		



REPLACEMENT FOR  
**COROLLA '08**

REPLACEMENT FOR  
**COROLLA '08**

REPLACEMENT FOR  
**CAMRY '2012**

<p><b>SL320308003</b> FOG LAMP L:81220-06050 R:81210-06052</p> 	<p><b>SL320308053-01</b> F.R BUMPER SUPPORT ARM L:57014-12050 R:57013-12050</p> 	<p><b>SL320212042-L</b> AIR CLEANER INTAKE 17750-0H050</p> 
<p><b>SL320308042-01</b> '08-'13 AIR CLEANER 65 mm 17700-21181 17700-74380 17700-0D220</p> 	<p><b>SL320308059-01</b> R.R BUMPER SUPPORT ARM L: R:</p> 	
<p><b>SL320308042-02</b> '08-'13 AIR CLEANER 70 mm 17700-21181 17700-74380 17700-0D220</p> 	<p><b>SL320308010</b> SUPPORT</p> 	
<p><b>SL320308041-01</b> FAN 7B 16361-22130</p> 	<p><b>SL320308135</b> FUEL TANK CAP 77350-12510</p> 	
<p><b>SL320308128-R</b> RR. BUMPER ABSORBER 52615-121160</p> 		
<p><b>SL320308136</b> INSULATOR HOOD 53341-12290</p> 	<p><b>SL320305025 COROLLA '05</b> ENGINE PROTECT FOR 11212-21011 11212-21031</p> 	




REPLACEMENT FOR  
**CAMRY '07**

REPLACEMENT FOR  
**AVALON '01-'04**

REPLACEMENT FOR  
**AVALON '05-'07**

**SL320208037**

FAN SHROUD  
16711-OH140  
16711-28300



**SL320102003**

FOG LAMP W/O BULB  
L:81220-AC020  
R:81210-AC020



**SL320105003**

HEAD LAMP  
L:81150-AC050  
R:81110-AC050



**SL320208136**

INSULATOR HOOD  
53341-33120



**SL320102006**

BACK LAMP  
L:  
R:



**SL320208128-F**

FR. BUMPER ABSORBER  
52611-06050



**SL320102007**

GRILLE  
52611-06050



**SL320102007C**

GRILLE ALL CHROM

**SL320102024-R**

REAR FENDER INNER  
L:61668-AC020  
R:61667-AC020














REPLACEMENT FOR  
**LANCER '03-'06**

REPLACEMENT FOR  
**LANCER '07**

REPLACEMENT FOR  
**L300 '01**

<p><b>SL250803037</b> FAN SHROUD MR968365</p> 	<p><b>SL250811007</b> GRILLE BLACK 7450A118 7450A178</p> 	<p><b>SL250601003</b> FRONT LAMP L:MIT01AC77901LCD R:MIT01AC77902LCD</p> 
<p><b>SL250803024-R</b> REAR FENDER INNER L:MN126829 R:MN126830</p> 	<p><b>SL250811007-1</b> GRILLE CHROME&amp;GREY 7450A118 7450A178</p> 	
<p><b>SL250803043</b> GARNISH FR.DECK L:MR533285 R:MR533286</p> 	<p><b>SL250811007C</b> GRILLE ALL CHROM 7450A118 7450A178</p> 	
<p><b>SL250803135</b> CLIPS FOR DECK</p> 	<p><b>SL250811007-2</b> COVER GRILLE 7450A120</p> 	



REPLACEMENT FOR  
**AURIS**

REPLACEMENT FOR  
**AVENSIS**

REPLACEMENT FOR  
**YARIS**

<p><b>SL323407126</b>    <b>AURIS 07-11</b> BUMPER BRACET FR. L:52536-12100 R:52535-12080</p> 	<p><b>SL323503126</b>    <b>AVENSIS 03-06</b> BUMPER BRACET FR. L:52536-05020 R:52535-05020</p> 	<p><b>SL321603133</b>    <b>YARIS 03-06</b> COVER-BUMPER BR FR. 52721-0D010</p> 
<p><b>SL323407127</b>    <b>AURIS 07-11</b> BUMPER BRACET RR. L:52576-12150 R:52575-12150</p> 	<p><b>SL323503127</b>    <b>AVENSIS 03-06</b> BUMPER BRACET RR. L:52576-05030 R:52575-05030</p> 	<p><b>SL321607133</b>    <b>YARIS 07-09</b> COVER-BUMPER BR FR. 52127-52925</p> 
<p><b>SL323412126</b>    <b>AURIS 12-17</b> BUMPER BRACET FR. L:52536-02050 R:52535-02040</p> 	<p><b>SL323510015</b>    <b>AVENSIS 10-14</b> FOG LAMP CASE L:81482-05010 R:81481-05010</p> 	<p><b>SL321611126</b>    <b>YARIS 11-17</b> BUMPER BRACET FR. L:52536-0D090 R:52535-0D090</p> 
<p><b>SL323412127</b>    <b>AURIS 12-17</b> BUMPER BRACET RR. L:52576-02091 R:52575-02091</p> 		<p><b>SL321611127</b>    <b>YARIS 11-17</b> BUMPER BRACET RR. L:52576-0D130 R:52575-0D130</p> 
<p><b>SL323412130</b>    <b>AURIS 12-14</b> RR. BUMPER REFLECTOR L:81920-02090 R:81910-02270</p> 	<p><b>SL323416133</b>    <b>AURIS 16</b> COVER-BUMPER BR FR. L:52128-02420 R:52127-02430</p> 	
<p><b>SL323416130</b>    <b>AURIS 16</b> RR. BUMPER REFLECTOR L:81920-02260 R:81910-02260</p> 	<p><b>SL323416045</b>    <b>AURIS 16</b> RR. BUMPER MOULDING L:52682-02010 R:52681-02010</p> 	

REPLACEMENT FOR  
**BUMPER ABSORBER**

REPLACEMENT FOR  
**BUMPER ABSORBER**

REPLACEMENT FOR  
**BUMPER ABSORBER**

<p><b>SL320308128-R COROLLA 08</b> RR. BUMPER ABSORBER 52615-121160</p> 	<p><b>SL262507128-F VERSA 07</b> FR. BUMPER ABSORBER 62090-EM30A</p> 	<p><b>SL401310128-F RX270 10</b> FR. BUMPER ABSORBER 52611-48100</p> 
<p><b>SL320310128-F COROLLA 10</b> FR. BUMPER ABSORBER 52611-02250</p> 	<p><b>SL400310128-F ES240 10</b> FR. BUMPER ABSORBER 52611-33190</p> 	<p><b>SL401310128-R RX270 10</b> RR. BUMPER ABSORBER 52615-48130</p> 
<p><b>SL320314CN128-F COROLLA 14 CN</b> FR. BUMPER ABSORBER 52611-02220</p> 	<p><b>SL400413128-R ES250 13</b> RR. BUMPER ABSORBER 52615-33140</p> 	<p><b>SL401313128-F RX270 13</b> FR. BUMPER ABSORBER 52611-48140</p> 
<p><b>SL320208128-F CAMRY 07</b> FR. BUMPER ABSORBER 52611-06050</p> 	<p><b>SL400413128-F ES250 13</b> FR. BUMPER ABSORBER 52611-33220</p> 	
<p><b>SL320212CN128-F CAMRY 12 CN</b> FR. BUMPER ABSORBER 52611-06280</p> 	<p><b>SL400706128-F ES350 06</b> FR. BUMPER ABSORBER 52611-33170</p> 	
<p><b>SL320215CN128-F CAMRY 15 CN</b> FR. BUMPER ABSORBER 52611-06400</p> 	<p><b>SL400706128-R ES350 06</b> RR. BUMPER ABSORBER 52615-33130</p> 	



## DANYANG SAILING AUTO PARTS CO.,LTD

ADD:Jiedong Industry area, Jiepai Town Danyang city

Jiangsu Province China

TEL/FAX: +86-511-86388106

MOB: 0086-15952940702

WEB: [www.slautoparts.com](http://www.slautoparts.com)

E-MAIL: [kevin@slautoparts.com](mailto:kevin@slautoparts.com)